

VLMP Sample Date: 6/20/2011

Aquatic Plants: 5% to 25%

Volunteer Hours: .75

Amount of Rain (inches): 0

Wind Direction: SW

Cloud Cover: Overcast

Waves: Calm/Ripple

Lake Level: Above Normal

Lake Level Measure: 5

Gauge Reading: 0

Observations:

Additional Observations: Sago, Chara, spatterdock, coontail, Water lily, floating pondweed Filamentous algae at varying amounts based on location

Lake/Watershed Management:

Aquatic Exotic(s) Present

Eurasian Watermilfoil
Curlyleaf Pondweed
Common Carp

Volunteer(s) Assisting During Monitoring Trip

Kalstrup, Mike

Other People Assisting

Secchi Result(s)

Site #	Collection Time	Secchi Depth (nearest inch)	Secchi Visible on the Bottom	Secchi Hidden by Aquatic Plants	Color	Plant Coverage at Site	Total Depth (nearest 1/2 foot)
RTZP-1	14:00	99	No	No	8	0	30
RTZP-2	13:50	101	No	No	8	0	19
RTZP-3	14:14	62	No	No	8	2	5
RTZP-4	14:24	78	No	No	8	2	7